



Las Vegas Fire & Rescue
Fire Prevention Division

July 14, 2009

The current Risk Assessment has been established for the Moulin Rouge and surrounding adjacent property including addresses.

840 W. Bonanza
900 W. Bonanza
920 W. Bonanza
901 W. Mc Williams
1001 W. McWilliams
1100 W Mc Williams

General overall site status:

The gate nearest to the 840 / 900 W. bonanza address (South/East entrance) is open and not secured allowing free access. The West side of the (casino/tower sign) remaining building is open and accessible. The 840 / 900 building (hotel) is accessible with broken windows, removed doors, combustible materials present on the inside and outside of the building. Empty swimming pool is not covered or secured. Partially damaged and remaining buildings at 920 W. Bonanza Apartment buildings (North/West) are open and accessible for vagrants and or trespassers. Rear access to the site from W. McWilliams locked and inaccessible gate at this time. Two trailers are present behind the 840 / 900 address on site. There is carpet, furniture, removed electrical equipment, and air conditioning units present in this area to the property line to the Treeline senior condos/apartments (901 W. McWilliams accessible from H Street or Mc Williams)

Primary Hazard: Dangerous site conditions, limited access onto site, limited site security. There is a single guard, no appearance of roving unless someone appears on property.

Recommendation for site: Secure, provide additional; roving guards, secure all access points, remove all combustible materials from site.

840 and 900 W. Bonanza

Current Condition:

The posted building address as 900 W. Bonanza includes the tower sign and what remains of the casino facility. (CLV interactive map reflects as 840 W. Bonanza). Only the 40' tower sign is in place with structural support devices holding up what remains of the casino and the sign structure. The supports were placed into service as a result of a fire in 2003 that consumed the entire casino complex. This section of the building is open, not secure. The stand alone 840 W. Bonanza building is not secure with electrical and mechanical equipment removed.

Address has had Five emergency medical responses documented to this location as recent as 2008.

Primary Hazard: Collapse possible due to previous fires, asbestos material may be present in what remains of the remaining structure, additional hazard to emergency response staff to presumed vacant building.

Recommendation: Demo entire group of buildings, remove empty swimming pool.

920 W. Bonanza

Current Condition: This address consists of four standalone 2 story buildings. The first building facing W. bonanza and the second running North/South were most recently converted to apartment buildings. Both buildings are accessible, with major rehab and demo work started. This has left the buildings with no windows, doors, electrical equipment, or mechanical equipment.

Address had single response 04/06/2008. Buildings were vacant at the time.

Primary Hazard: Fire and safety hazards as the units not secure and open to the environment. Possible asbestos material present, safety risk to responding personnel as a result of building and site condition.

920 W. Bonanza (cont).

Current Condition: These are the two remaining 2 story buildings at the North of the complex running East / West. Buildings are unsecure with broken glass, mechanical and electrical equipment removed and visible damage to both buildings.

Primary Hazard: Fire and safety hazards as the units not secure and open to the environment. Possible asbestos material present, safety risk to responding personnel as a result of building and site condition.

Recommendation: Confirm no existence of asbestos and demo entire group of buildings.

1001 W. Mc Williams

Current Condition: Buildings appear to be vacant at this time. Buildings are boarded up with no outward signs of vagrants entering buildings. Site has limited access.

Address has had no reported fire or emergency responses reported.

Primary Hazard: As no site security is present the chance of fire as a result of intentionally set fire is high. Site has substantial amount of combustible material and plants in the center courtyard and surrounding areas.

Recommendation: Secure site, allow approved access to 840, 900, 920 W. bonanza and 901 W. McWilliams locations, remove all combustible material and provide additional security.

901 W. Mc Williams

Current Condition: Two groups of single story buildings. The units designated as "Treeline Senior Condos" (closest to H Street) appear to only have approximately ½ of the units occupied, others are boarded and secured. Limited access only from H Street. Secondary access is through 1001 W. McWilliams location. Secondary emergency access gate is locked and secured. Available water supply is on West side of locked gate and not accessible for use in the event of fire in occupied units to East.

Primary Hazard: Fire hazard, delay in emergency response due to limited access. Substantial fire loss as a result of limited available water supply. Site has substantial fire loading due to no maintenance of landscaping.

Recommendation: Secure site and provide additional roving security, provide approved access to fire hydrants.

The second group of single story apartment buildings to the West of the Condo buildings appears to have partial occupancy at this time. Access is a single opening from W. McWilliams. Numerous locations have broken windows and have the appearance of been vandalized.

Primary Hazard: Fire hazard, delay in emergency response due to limited access.

Address had eleven Emergency medical calls and four fire responses documented in the last two years.

Recommendation: Open additional emergency response access, remove all combustible material from unoccupied units, and provide address numbers for emergency response.