

A. 8920 Desert Mound
B. 8924 Desert Mound
C. 9000 Desert Mound

Reena Benbow

12/08/90



**WESTERN
TECHNOLOGIES
INC.**

3611 West Tompkins Avenue
Las Vegas, Nevada 89103
(702) 798-8050

FIELD REPORT

**REVIEW OF FOUNDATION CONDITIONS
(POST ON JOBSITE)**

Client DEL WEBB

Project SUN CITY

Location Summerlin

Prime Contractor CURTIS - JONES

Job No. 47495090

Lab./Invoice No.

Report No. Date 4-5-89

Time of Report

Superintendent FRANKY SANCHEZ

In accordance with the request of DEL WEBB
a review of the excavations for foundations on the above referenced project was made.

The purpose of the review was to:

- ☒ Verify conformity of depths of foundation excavations to requirements of project plans and/or specifications.
- ☐ Verify that the undisturbed bearing soils exposed by the excavations were of the nature and condition anticipated by WT Soil Engineering Report No.
- ☒ Check for debris and/or loose or disturbed soils in bottom of foundations excavations.
- ☒ Check conformity of foundation dimensions with project plan requirements.
- ☒ Check conformity of foundation reinforcement in the excavations with project requirements.
- ☐ Other

With the exceptions stated below, the review revealed that:

- ☒ Depth of foundation excavations (did) (did not) meet project requirements.
- ☐ Soil bearing recommendations presented in WT Soil Engineering Report No. for foundations bearing on (do) (do not) remain applicable.
- ☒ Foundation excavations (did) (did not) contain debris and/or loose or disturbed soil. Subsequent debris, loose or disturbed soil should be removed from bottoms of excavations before placing concrete.
- ☒ Excavation dimensions (did) (did not) meet minimum project plan requirements for foundation dimensions.
- ☒ Sizes and locations of foundation reinforcing steel in the excavations (did) (did not) meet project plan requirements.
- ☐ Other

The following foundation excavations were reviewed:

Excavation #
607, 708, 79, 100, 101, 102, 103, 104, 105
Sec. 65, 66, 67, 68, 69, 70, 71, 72

Exceptions and/or remarks:

Review By



**WESTERN
TECHNOLOGIES
INC.**

3611 West Tompkins Avenue
Las Vegas, Nevada 89103
(702) 798-8050

FIELD REPORT

**REVIEW OF FOUNDATION CONDITIONS
(POST ON JOBSITE)**

Client DEL WEBB

Project SUN CITY

Location SUMNER

Prime Contractor CURTIS - JONES

Job No. 41495090

Lab./Invoice No. 1

Report No. 1 Date 7-5-89

Time of Report 10:00 AM

Superintendent RANDY SCHAUS

In accordance with the request of DEL WEBB
a review of the excavations for foundations on the above referenced project was made.

The purpose of the review was to:

- ☒ Verify conformity of depths of foundation excavations to requirements of project plans and/or specifications.
- ☐ Verify that the undisturbed bearing soils exposed by the excavations were of the nature and condition anticipated by WT Soil Engineering Report No. 1
- ☒ Check for debris or loose or disturbed soils in bottom of foundations excavations.
- ☒ Check conformity of foundation dimensions with project plan requirements.
- ☒ Check conformity of foundation reinforcement in the excavations with project requirements.
- ☐ Other 1

With the exceptions stated below, the review revealed that:

- ☒ Depth of foundation excavations (did) (did not) meet project requirements.
- ☐ Soil bearing recommendations presented in WT Soil Engineering Report No. 1 for foundations bearing on (do) (do not) remain applicable.
- ☒ Foundation excavations (did) (did not) contain debris and/or loose or disturbed soil. Subsequent debris, loose or disturbed soil should be removed from bottoms of excavations before placing concrete.
- ☒ Excavation dimensions (did) (did not) meet minimum project plan requirements for foundation dimensions.
- ☒ Sizes and locations of foundation reinforcing steel in the excavations (did) (did not) meet project plan requirements.
- ☐ Other 1

The following foundation excavations were reviewed:

Lot 17, 18, 19, 100, 101, 102, 104, 105
Sec 16S, 16E, 67, 68, 69, 70, 71, 72

Exceptions and/or remarks:

Review By 1



**WESTERN
TECHNOLOGIES
INC.**

3611 West Tompkins Avenue
Las Vegas, Nevada 89103
(702) 798-8050

FIELD REPORT

**REVIEW OF FOUNDATION CONDITIONS
(POST ON JOBSITE)**

Client DEL WEBB

Project San City

Location Sumner

Prime Contractor CURTIS - JONES

Job No. 41495090

Lab./Invoice No.

Report No. Date 7-5-89

Time of Report

Superintendent FRANKY SANCHEZ

In accordance with the request of DEL WEBB
a review of the excavations for foundations on the above referenced project was made.

The purpose of the review was to:

- ☒ Verify conformity of depths of foundation excavations to requirements of project plans and/or specifications.
- ☐ Verify that the undisturbed bearing soils exposed by the excavations were of the nature and condition anticipated by WT Soil Engineering Report No.
- ☒ Check for debris and/or loose or disturbed soils in bottom of foundations excavations.
- ☒ Check conformity of foundation dimensions with project plan requirements.
- ☒ Check conformity of foundation reinforcement in the excavations with project requirements.

☐ Other

With the exceptions stated below, the review revealed that:

- ☒ Depth of foundation excavations (did) (did not) meet project requirements.
- ☐ Soil bearing recommendations presented in WT Soil Engineering Report No. for foundations bearing on (do) (do not) remain applicable.
- ☒ Foundation excavations (did) (did not) contain debris and/or loose or disturbed soil. Subsequent debris, loose or disturbed soil should be removed from bottoms of excavations before placing concrete.
- ☒ Excavation dimensions (did) (did not) meet minimum project plan requirements for foundation dimensions.
- ☒ Sizes and locations of foundation reinforcing steel in the excavations (did) (did not) meet project plan requirements.

☐ Other

The following foundation excavations were reviewed:

LOT 38, 39, 100, 101, 102, 103, 104, 105
SEC 65, 66, 67, 68, 69, 70, 71, 72

Exceptions and/or remarks:

Review By