

A. 8920 Desert Mound

B. 8924 Desert Mound.

C. 9000 Desert Mound

Reena Benbow 12/08/90



WESTERN TECHNOLOGIES INC.

3611 West Tompkins Avenue
Las Vegas, Nevada 89103
(702) 798-8050

FIELD REPORT

REVIEW OF FOUNDATION CONDITIONS
(POST ON JOBSITE)

Client DEL WEBB

Project Sun City

Location Summerlin

Prime Contractor Curtis - Jones

Job No. 48495090

Lab./Invoice No.

Report No. Date 4-5-89

Time of Report

Superintendent Randy Scharis

In accordance with the request of DEL WEBB a review of the excavations for foundations on the above referenced project was made.

The purpose of the review was to:

- Verify conformity of depths of foundation excavations to requirements of project plans and/or specifications.
- Verify that the undisturbed bearing soils exposed by the excavations were of the nature and condition anticipated by WT Soil Engineering Report No.
- Check for debris and/or loose or disturbed soils in bottom of foundations excavations.
- Check conformity of foundation dimensions with project plan requirements.
- Check conformity of foundation reinforcement in the excavations with project requirements.
- Other

With the exceptions stated below, the review revealed that:

- Depth of foundation excavations (did) (did not) meet project requirements.
- Soil bearing recommendations presented in WT Soil Engineering Report No. for foundations bearing on (do) (do not) remain applicable.
- Foundation excavations (did) (did not) contain debris and/or loose or disturbed soil. Subsequent debris, loose or disturbed soil should be removed from bottoms of excavations before placing concrete.
- Excavation dimensions (did) (did not) meet minimum project plan requirements for foundation dimensions.
- Sizes and locations of foundation reinforcing steel in the excavations (did) (did not) meet project plan requirements.
- Other

The following foundation excavations were reviewed:

Excavation #s:
607, 78, 79, 100, 101, 102, 103, 104, 105
Sec. 65, 66, 67, 68, 69, 70, 71, 72

Exceptions and/or remarks:

Review By



**WESTERN
TECHNOLOGIES
INC.**

3611 West Tompkins Avenue
Las Vegas, Nevada 89103
(702) 798-8050

FIELD REPORT

**REVIEW OF FOUNDATION CONDITIONS
(POST ON JOBSITE)**

Client DEL WEBB

Project SUN CITY

Location SUNSHINE

Prime Contractor CURTIS - JONES

Job No. 41495090

Lab./Invoice No. J

Report No. _____ Date 7-5-89

Time of Report _____

Superintendent RANDY SCHMIDT

In accordance with the request of DEL WEBB
a review of the excavations for foundations on the above referenced project was made.

The purpose of the review was to:

- Verify conformity of depths of foundation excavations to requirements of project plans and/or specifications.
- Verify that the undisturbed bearing soils exposed by the excavations were of the nature and condition anticipated by WT Soil Engineering Report No. _____
- Check for debris or loose or disturbed soils in bottom of foundations excavations.
- Check conformity of foundation dimensions with project plan requirements.
- Check conformity of foundation reinforcement in the excavations with project requirements.
- Other _____

With the exceptions stated below, the review revealed that:

- Depth of foundation excavations (did) (did not) meet project requirements.
- Soil bearing recommendations presented in WT Soil Engineering Report No. _____ for foundations bearing on _____ (do) (do not) remain applicable.
- Foundation excavations (did) (did not) contain debris and/or loose or disturbed soil. Subsequent debris, loose or disturbed soil should be removed from bottoms of excavations before placing concrete.
- Excavation dimensions (did) (did not) meet minimum project plan requirements for foundation dimensions.
- Sizes and locations of foundation reinforcing steel in the excavations (did) (did not) meet project plan requirements.
- Other _____

The following foundation excavations were reviewed:

Lot 78, 79, 100, 101, 102, 104, 105
Sec 165, 66, 67, 68, 69, 70, 71, 72

Exceptions and/or remarks:

Review By _____



**WESTERN
TECHNOLOGIES
INC.**

3611 West Tompkins Avenue
Las Vegas, Nevada 89103
(702) 798-8050

FIELD REPORT

**REVIEW OF FOUNDATION CONDITIONS
(POST ON JOBSITE)**

Client *DEL WEBB*

Project *Sun City*

Location *Summerlin*

Prime Contractor *CURTIS - JONES*

Job No. *211495090*

Lab./Invoice No.

Report No. Date *7-5-89*

Time of Report

Superintendent *FANDY SANCHEZ*

In accordance with the request of *DEL WEBB*
a review of the excavations for foundations on the above referenced project was made.

The purpose of the review was to:

- Verify conformity of depths of foundation excavations to requirements of project plans and/or specifications.
- Verify that the undisturbed bearing soils exposed by the excavations were of the nature and condition anticipated by WT Soil Engineering Report No.
- Check for debris and/or loose or disturbed soils in bottom of foundations excavations.
- Check conformity of foundation dimensions with project plan requirements.
- Check conformity of foundation reinforcement in the excavations with project requirements.
- Other

With the exceptions stated below, the review revealed that:

- Depth of foundation excavations *(did)* (did not) meet project requirements.
- Soil bearing recommendations presented in WT Soil Engineering Report No. _____ for foundations bearing on (do) (do not) remain applicable.
- Foundation excavations *(do)* *(did not)* contain debris and/or loose or disturbed soil. Subsequent debris, loose or disturbed soil should be removed from bottoms of excavations before placing concrete.
- Excavation dimensions *(did)* (did not) meet minimum project plan requirements for foundation dimensions.
- Sizes and locations of foundation reinforcing steel in the excavations *(did)* (did not) meet project plan requirements.
- Other

The following foundation excavations were reviewed:

Lot 38, 39, 100, 101, 102, 103, 104, 105
Sec 65, 66, 67, 68, 69, 70, 71, 72

Exceptions and/or remarks:

Review By