

28 Cedar

JACKIE B.

2/10/86

BUILDING DEPARTMENT
CITY OF LAS VEGAS
M + M ELECTRIC
CORRECTION NOTICE

Job Located at 28th CEDAR

I have this day inspected this structure
and these premises and have found the following
violations of City and/or State laws governing
same:

ALL CLAMPS HOLDING
ROMEX TO BE TIGHTENED

OR R.W.

You are hereby notified to correct
above violation and call for re-inspection.

Date

2-5-86 Robert Smith
Inspector

23.03

Do not remove this tag!

28th ST
CEDAR

F. Zeno Martin Associates, Architects, P.C.

F. ZENO MARTIN ASSOCIATES, ARCHITECTS, P.C.

17348 WEST TWELVE MILE ROAD SUITE 100
SOUTHFIELD, MICHIGAN 48076 (313) 557-1062

February 5, 1988.

Mr. & Mrs. John
Development Company
1341 East. Fremont
Las Vegas, Nevada 89101.

Re: Elmwood Apartments
Cedar and 28th Streets
Las Vegas, Nevada
File No. 8235

Dear Cy,


Based upon our recent conversation, I submit this letter of understanding and approval regarding the specified 1/2" fiberboard sheathing detailed on the drawings for the above referenced project.

It is my understanding that the entire first floor, including the stair corridors, will be sheathed with 1/2" plywood, as indicated on the drawings. It is also my understanding that the second and third floor stair corridors, in addition to the corner bracing on those floors, will be sheathed with 1/2" plywood.

Therefore, I do not feel that the 1/2" fiberboard sheathing, which is common here in Michigan, is necessary since you are going to apply wire lath directly to the studs for the final surface application.

If I can be of any further assistance in this matter, do not hesitate to contact this office.

Sincerely,



Frank Z. Martin, A.I.A., N.C.A.R.B. Certificate
F. ZENO MARTIN ASSOCIATES, ARCHITECTS, P.C.

FZM/gl