

SHEET
SHEET #


1
2
3
4
5
6
7
8
9
10
11



SHEET #	SHEET DESCRIPTION
---------	-------------------

1	C1	COVER SHEET	
2	C2	VICINITY MAP	
3	C3	GENERAL NOTES SHEET	
4	C4	QUANTITY SHEET	
5	C5	MASTER UTILITY PLAN	
6	G1	GRADING PLAN	
7	S1	STREET PLAN & PROFILE - GRAND TETON	
8	S2	STREET PLAN & PROFILE - DURANGO DRIVE	
9	S3	TYPICAL STREET SECTIONS, GRADING & WALL DETAILS	
10	TS1	SIGNAL, STRIPING & STREET LIGHTING PLAN	
11	SS1	SANITARY SEWER PLAN AND PROFILE	

	SHEET C2 2 OF 11 SHEETS DRAWING NO. 1078-4660		DRAWN BY: JMC _____ NOV. 1989		SHEET VICINITY MAP		SOUTHWEST DESERT EQUITIES 1320 NORTH BUFFALO DRIVE SUITE 205 LAS VEGAS, NEVADA 89128 (702) 395-4734	
	CHECKED BY: VAV _____ NOV. 1989		DESIGNED BY: VAV _____ NOV. 1989		GRAND TETON/DURANGO		vtm novads 2727 SOUTH RAINBOW BOULEVARD LAS VEGAS, NEVADA 89102-5148 PH. (702) 873-7550 FAX (702) 382-2597 CONSULTING ENGINEERS • PLANNERS • LAND SURVEYORS	
PROJECT NO: 5670		SCALE: 1"=1' HORIZ. VERT.		TITLE GRAND TETON/DURANGO		2727 SOUTH RAINBOW BOULEVARD LAS VEGAS, NEVADA 89102-5148 PH. (702) 873-7550 FAX (702) 382-2597 CONSULTING ENGINEERS • PLANNERS • LAND SURVEYORS		REV _____ DATE _____ BY _____

[illegible][illegible]

1000

1. The first step is to identify the problem. In this case, the problem is that the company is not meeting its sales targets.

1

1



100

Figure 1

