

Seaway Pinnits for 17 houses
6231 - 6325 Cambera Ave
204 - 2136 Conchita St.

G. Gatewood 2/7/79

CITY OF LAS VEGAS, NEVADA
DEPARTMENT OF BUILDING & SAFETY

**RECEIPT
FOR
SEWER CONNECTION FEE**

17 HOUSES
6231 thru 6525 Cambria Avenue
JOB ADDRESS: 2204 thru 2136 Conchita Street
1 - 13 Blk. 9
LOT 11 - 14 BLOCK 5 SUBDIVISION Charleston Heights 51-C
OWNER'S NAME: BECKER & SONS

QUANTITY	OCCUPANCY	UNIT FEE	AMOUNT
17	SINGLE FAMILY RESIDENCES		\$2,550.00

PAID BY: Becker & Sons

TOTAL \$2,550.00

Less Credit

TOTAL FEE \$ 2,550.00

*Credit for existing sewer is applied to the new sewer connection fee based on previous type of occupancy and only when the new occupancy requires an additional fee.

This receipt does not authorize the owner or his representative to start any work without obtaining a plumbing permit.

DEPARTMENT OF BUILDING & SAFETY

DATE

RECEIPT NO. 2604

SEWER FEE \$ 2550

672102

41NANC RECEIPT 00
SEWR \$2550.00
STL \$ 2550.00
STL \$ 2550.00
TUTL \$ 2550.00
CHEK \$ 2550.00
AN2604 SR#001/01
CITY - LAS VEGAS
BLDG & SAFETY
01/07/78
MACHINE VALIDATED

G. Gatewood 2/7/79

CITY OF LAS VEGAS, NEVADA
DEPARTMENT OF BUILDING & SAFETY

**RECEIPT
FOR
SEWER CONNECTION FEE**

JOB ADDRESS: Cambria Ave OWNER'S NAME: Vista Verde Homes
LOT 13 BLOCK 1 SUBDIVISION Charleston Heights Tract 51-c

QUANTITY	OCCUPANCY	UNIT FEE	AMOUNT
	6300-6304-6308-6312	150	1950
13	6316-6320-6324-6350		
	6246-6242-6238-6234		
	6230		

PAID BY: _____

TOTAL 1950

Less Credit 0

TOTAL FEE \$ 1950

*Credit for existing sewer is applied to the new sewer connection fee based on previous type of occupancy and only when the new occupancy requires an additional fee.

This receipt does not authorize the owner or his representative to start any work without obtaining a plumbing permit.

DEPARTMENT OF BUILDING & SAFETY

SEWER \$ 19.50

STL \$ 1930.50

TOTAL \$ 1950.00

RECEIVED \$ 1950.00

RECEIVED \$ 1950.00

RECEIVED \$ 1950.00

RECEIVED \$ 1950.00

RECEIVED \$ 1950.00

RECEIVED \$ 1950.00

RECEIVED \$ 1950.00

RECEIVED \$ 1950.00

RECEIPT NO. 4817

73103

MUST BE MACHINE VALIDATED