

TORREY PINES VILLAS

Block 1

Lot 1	6401	Hill View Avenue
2	6405	" " "
3	6409	" " "
4	6413	" " "
5	6417	" " "
6	6421	" " "
7	6425	" " "
8	6429	" " "
9	6433	" " "
10	6501	" " "
11	6505	" " "
12	6509	" " "
13	6513	" " "
14	6517	" " "
15	6521	" " "
16	6525	" " "
17	6529	" " "
18	6533	" " "
19	6537	" " "

Block 2

Lot 1	401	Plainview Street
2	405	" "
3	409	" "

Block 3

Lot 1	409	Cactus Bloom Lane
2	405	" " "
3	401	" " "
4	6420	Hill View Avenue
5	6424	" " "
6	6428	" " "
7	6432	" " "
8	6500	" " "
9	6504	" " "
10	6508	" " "
11	6512	" " "
12	6516	" " "
13	6520	" " "
14	6524	" " "
15	6528	" " "
16	6525	Villa Mesa Drive
17	6521	" " "
18	6517	" " "
19	6513	" " "
20	6509	" " "
21	6505	" " "
22	6501	" " "
23	6429	" " "
24	6425	" " "
25	6421	" " "
26	6417	" " "
27	6413	" " "

Block 4

Lot 1	501	Cactus Bloom Lane
2	505	" " "
3	509	" " "
4	513	" " "
5	601	" " "
6	605	" " "
7	609	" " "
8	701	" " "
9	705	" " "
10	709	" " "
11	801	" " "
12	805	" " "
13	809	" " "

Block 5

Lot 1	401	Torrey Pines Blvd
2	405	" " "
3	409	" " "
4	413	" " "
5	417	" " "
6	501	" " "
7	505	" " "
8	509	" " "
9	601	" " "
10	605	" " "
11	609	" " "
12	701	" " "
13	705	" " "
14	709	" " "
15	801	" " "
16	805	" " "
17	809	" " "
18	808	Cactus Bloom Lane
19	804	" " "
20	800	" " "
21	708	" " "
22	704	" " "
23	700	" " "
24	608	" " "
25	604	" " "
26	600	" " "
27	512	" " "
28	508	" " "
29	504	" " "
30	500	" " "
31	412	" " "
32	408	" " "
33	404	" " "
34	400	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
	6401	6405	6409	6413	6417	6421	6425	6429	6433	6501	6505	6509	6513	6517	6521	6525	6529	6533	6537
	Hill View Avenue	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"

Block 4

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13
	501	505	509	513	601	605	609	701	705	709	801	805	809
	Cactus Bloom Lane	"	"	"	"	"	"	"	"	"	"	"	"

Block 5

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34
	401	405	409	413	417	501	505	509	601	605	609	701	705	709	801	805	809	808	804	800	708	704	700	608	604	600	512	508	504	500	412	408	404	400
	Torrey Pines Blvd	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	Cactus Bloom Lane	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	

Block 2

Lot	1	2	3
	401	405	409
	Plainview Street	"	"

Block 3

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27
	409	405	401	6420	6424	6428	6432	6500	6504	6508	6512	6516	6520	6524	6528	6525	6521	6517	6513	6509	6505	6501	6429	6425	6421	6417	6413
	Cactus Bloom Lane	"	"	Hill View Avenue	"	"	"	"	"	"	"	"	"	"	"	Villa Mesa Drive	"	"	"	"	"	"	"	"	"	"	"

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot	1	6401	Hill View Avenue
	2	6405	" " "
	3	6409	" " "
	4	6413	" " "
	5	6417	" " "
	6	6421	" " "
	7	6425	" " "
	8	6429	" " "
	9	6433	" " "
	10	6501	" " "
	11	6505	" " "
	12	6509	" " "
	13	6513	" " "
	14	6517	" " "
	15	6521	" " "
	16	6525	" " "
	17	6529	" " "
	18	6533	" " "
	19	6537	" " "

Block 2

Lot	1	401	Plainview Street
	2	405	" "
	3	409	" "

Block 3

Lot	1	409	Cactus Bloom Lane
	2	405	" " "
	3	401	" " "
	4	6420	Hill View Avenue
	5	6424	" " "
	6	6428	" " "
	7	6432	" " "
	8	6500	" " "
	9	6504	" " "
	10	6508	" " "
	11	6512	" " "
	12	6516	" " "
	13	6520	" " "
	14	6524	" " "
	15	6528	" " "
	16	6525	Villa Mesa Drive
	17	6521	" " "
	18	6517	" " "
	19	6513	" " "
	20	6509	" " "
	21	6505	" " "
	22	6501	" " "
	23	6429	" " "
	24	6425	" " "
	25	6421	" " "
	26	6417	" " "
	27	6413	" " "

Block 4

Lot	1	501	Cactus Bloom Lane
	2	505	" " "
	3	509	" " "
	4	513	" " "
	5	601	" " "
	6	605	" " "
	7	609	" " "
	8	701	" " "
	9	705	" " "
	10	709	" " "
	11	801	" " "
	12	805	" " "
	13	809	" " "

Block 5

Lot	1	401	Torrey Pines Blvd
	2	405	" " "
	3	409	" " "
	4	413	" " "
	5	417	" " "
	6	501	" " "
	7	505	" " "
	8	509	" " "
	9	601	" " "
	10	605	" " "
	11	609	" " "
	12	701	" " "
	13	705	" " "
	14	709	" " "
	15	801	" " "
	16	805	" " "
	17	809	" " "
	18	808	Cactus Bloom Lane
	19	804	" " "
	20	800	" " "
	21	708	" " "
	22	704	" " "
	23	700	" " "
	24	608	" " "
	25	604	" " "
	26	600	" " "
	27	512	" " "
	28	508	" " "
	29	504	" " "
	30	500	" " "
	31	412	" " "
	32	408	" " "
	33	404	" " "
	34	400	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot	1	6401	Hill View Avenue
	2	6405	" " "
	3	6409	" " "
	4	6413	" " "
	5	6417	" " "
	6	6421	" " "
	7	6425	" " "
	8	6429	" " "
	9	6433	" " "
	10	6501	" " "
	11	6505	" " "
	12	6509	" " "
	13	6513	" " "
	14	6517	" " "
	15	6521	" " "
	16	6525	" " "
	17	6529	" " "
	18	6533	" " "
	19	6537	" " "

Block 4

Lot	1	501	Cactus Bloom Lane
	2	505	" " "
	3	509	" " "
	4	513	" " "
	5	601	" " "
	6	605	" " "
	7	609	" " "
	8	701	" " "
	9	705	" " "
	10	709	" " "
	11	801	" " "
	12	805	" " "
	13	809	" " "

Block 5

Lot	1	401	Torrey Pines Blvd
	2	405	" " "
	3	409	" " "
	4	413	" " "
	5	417	" " "
	6	501	" " "
	7	505	" " "
	8	509	" " "
	9	601	" " "
	10	605	" " "
	11	609	" " "
	12	701	" " "
	13	705	" " "
	14	709	" " "
	15	801	" " "
	16	805	" " "
	17	809	" " "
	18	808	Cactus Bloom Lane
	19	804	" " "
	20	800	" " "
	21	708	" " "
	22	704	" " "
	23	700	" " "
	24	608	" " "
	25	604	" " "
	26	600	" " "
	27	512	" " "
	28	508	" " "
	29	504	" " "
	30	500	" " "
	31	412	" " "
	32	408	" " "
	33	404	" " "
	34	400	" " "

Block 2

Lot	1	401	Plainview Street
	2	405	" " "
	3	409	" " "

Block 3

Lot	1	409	Cactus Bloom Lane
	2	405	" " "
	3	401	" " "
	4	6420	Hill View Avenue
	5	6424	" " "
	6	6428	" " "
	7	6432	" " "
	8	6500	" " "
	9	6504	" " "
	10	6508	" " "
	11	6512	" " "
	12	6516	" " "
	13	6520	" " "
	14	6524	" " "
	15	6528	" " "
	16	6525	Villa Mesa Drive
	17	6521	" " "
	18	6517	" " "
	19	6513	" " "
	20	6509	" " "
	21	6505	" " "
	22	6501	" " "
	23	6429	" " "
	24	6425	" " "
	25	6421	" " "
	26	6417	" " "
	27	6413	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot	1	6401	Hill View Avenue
	2	6405	" " "
	3	6409	" " "
	4	6413	" " "
	5	6417	" " "
	6	6421	" " "
	7	6425	" " "
	8	6429	" " "
	9	6433	" " "
	10	6501	" " "
	11	6505	" " "
	12	6509	" " "
	13	6513	" " "
	14	6517	" " "
	15	6521	" " "
	16	6525	" " "
	17	6529	" " "
	18	6533	" " "
	19	6537	" " "

Block 4

Lot	1	501	Cactus Bloom Lane
	2	505	" " "
	3	509	" " "
	4	513	" " "
	5	601	" " "
	6	605	" " "
	7	609	" " "
	8	701	" " "
	9	705	" " "
	10	709	" " "
	11	801	" " "
	12	805	" " "
	13	809	" " "

Block 5

Lot	1	401	Torrey Pines Blvd
	2	405	" " "
	3	409	" " "
	4	413	" " "
	5	417	" " "
	6	501	" " "
	7	505	" " "
	8	509	" " "
	9	601	" " "
	10	605	" " "
	11	609	" " "
	12	701	" " "
	13	705	" " "
	14	709	" " "
	15	801	" " "
	16	805	" " "
	17	809	" " "
	18	808	Cactus Bloom Lane
	19	804	" " "
	20	800	" " "
	21	708	" " "
	22	704	" " "
	23	700	" " "
	24	608	" " "
	25	604	" " "
	26	600	" " "
	27	512	" " "
	28	508	" " "
	29	504	" " "
	30	500	" " "
	31	412	" " "
	32	408	" " "
	33	404	" " "
	34	400	" " "

Block 2

Lot	1	401	Plainview Street
	2	405	" " "
	3	409	" " "

Block 3

Lot	1	409	Cactus Bloom Lane
	2	405	" " "
	3	401	" " "
	4	6420	Hill View Avenue
	5	6424	" " "
	6	6428	" " "
	7	6432	" " "
	8	6500	" " "
	9	6504	" " "
	10	6508	" " "
	11	6512	" " "
	12	6516	" " "
	13	6520	" " "
	14	6524	" " "
	15	6528	" " "
	16	6525	Villa Mesa Drive
	17	6521	" " "
	18	6517	" " "
	19	6513	" " "
	20	6509	" " "
	21	6505	" " "
	22	6501	" " "
	23	6429	" " "
	24	6425	" " "
	25	6421	" " "
	26	6417	" " "
	27	6413	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot 1	6401	Hill View Avenue
2	6405	" " "
3	6409	" " "
4	6413	" " "
5	6417	" " "
6	6421	" " "
7	6425	" " "
8	6429	" " "
9	6433	" " "
10	6501	" " "
11	6505	" " "
12	6509	" " "
13	6513	" " "
14	6517	" " "
15	6521	" " "
16	6525	" " "
17	6529	" " "
18	6533	" " "
19	6537	" " "

Block 2

Lot 1	401	Plainview Street
2	405	" "
3	409	" "

Block 3

Lot 1	409	Cactus Bloom Lane
2	405	" " "
3	401	" " "
4	6420	Hill View Avenue
5	6424	" " "
6	6428	" " "
7	6432	" " "
8	6500	" " "
9	6504	" " "
10	6508	" " "
11	6512	" " "
12	6516	" " "
13	6520	" " "
14	6524	" " "
15	6528	" " "
16	6525	Villa Mesa Drive
17	6521	" " "
18	6517	" " "
19	6513	" " "
20	6509	" " "
21	6505	" " "
22	6501	" " "
23	6429	" " "
24	6425	" " "
25	6421	" " "
26	6417	" " "
27	6413	" " "

Block 4

Lot 1	501	Cactus Bloom Lane
2	505	" " "
3	509	" " "
4	513	" " "
5	601	" " "
6	605	" " "
7	609	" " "
8	701	" " "
9	705	" " "
10	709	" " "
11	801	" " "
12	805	" " "
13	809	" " "

Block 5

Lot 1	401	Torrey Pines Blvd
2	405	" " "
3	409	" " "
4	413	" " "
5	417	" " "
6	501	" " "
7	505	" " "
8	509	" " "
9	601	" " "
10	605	" " "
11	609	" " "
12	701	" " "
13	705	" " "
14	709	" " "
15	801	" " "
16	805	" " "
17	809	" " "
18	808	Cactus Bloom Lane
19	804	" " "
20	800	" " "
21	708	" " "
22	704	" " "
23	700	" " "
24	608	" " "
25	604	" " "
26	600	" " "
27	512	" " "
28	508	" " "
29	504	" " "
30	500	" " "
31	412	" " "
32	408	" " "
33	404	" " "
34	400	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot 1	6401	Hill View Avenue
2	6405	" " "
3	6409	" " "
4	6413	" " "
5	6417	" " "
6	6421	" " "
7	6425	" " "
8	6429	" " "
9	6433	" " "
10	6501	" " "
11	6505	" " "
12	6509	" " "
13	6513	" " "
14	6517	" " "
15	6521	" " "
16	6525	" " "
17	6529	" " "
18	6533	" " "
19	6537	" " "

Block 2

Lot 1	401	Plainview Street
2	405	" "
3	409	" "

Block 3

Lot 1	409	Cactus Bloom Lane
2	405	" " "
3	401	" " "
4	6420	Hill View Avenue
5	6424	" " "
6	6428	" " "
7	6432	" " "
8	6500	" " "
9	6504	" " "
10	6508	" " "
11	6512	" " "
12	6516	" " "
13	6520	" " "
14	6524	" " "
15	6528	" " "
16	6525	Villa Mesa Drive
17	6521	" " "
18	6517	" " "
19	6513	" " "
20	6509	" " "
21	6505	" " "
22	6501	" " "
23	6429	" " "
24	6425	" " "
25	6421	" " "
26	6417	" " "
27	6413	" " "

Block 4

Lot 1	501	Cactus Bloom Lane
2	505	" " "
3	509	" " "
4	513	" " "
5	601	" " "
6	605	" " "
7	609	" " "
8	701	" " "
9	705	" " "
10	709	" " "
11	801	" " "
12	805	" " "
13	809	" " "

Block 5

Lot 1	401	Torrey Pines Blvd
2	405	" " "
3	409	" " "
4	413	" " "
5	417	" " "
6	501	" " "
7	505	" " "
8	509	" " "
9	601	" " "
10	605	" " "
11	609	" " "
12	701	" " "
13	705	" " "
14	709	" " "
15	801	" " "
16	805	" " "
17	809	" " "
18	808	Cactus Bloom Lane
19	804	" " "
20	800	" " "
21	708	" " "
22	704	" " "
23	700	" " "
24	608	" " "
25	604	" " "
26	600	" " "
27	512	" " "
28	508	" " "
29	504	" " "
30	500	" " "
31	412	" " "
32	408	" " "
33	404	" " "
34	400	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot 1	6401	Hill View Avenue
2	6405	" " "
3	6409	" " "
4	6413	" " "
5	6417	" " "
6	6421	" " "
7	6425	" " "
8	6429	" " "
9	6433	" " "
10	6501	" " "
11	6505	" " "
12	6509	" " "
13	6513	" " "
14	6517	" " "
15	6521	" " "
16	6525	" " "
17	6529	" " "
18	6533	" " "
19	6537	" " "

Block 2

Lot 1	401	Plainview Street
2	405	" " "
3	409	" " "

Block 3

Lot 1	409	Cactus Bloom Lane
2	405	" " "
3	401	" " "
4	6420	Hill View Avenue
5	6424	" " "
6	6428	" " "
7	6432	" " "
8	6500	" " "
9	6504	" " "
10	6508	" " "
11	6512	" " "
12	6516	" " "
13	6520	" " "
14	6524	" " "
15	6528	" " "
16	6525	Villa Mesa Drive
17	6521	" " "
18	6517	" " "
19	6513	" " "
20	6509	" " "
21	6505	" " "
22	6501	" " "
23	6429	" " "
24	6425	" " "
25	6421	" " "
26	6417	" " "
27	6413	" " "

Block 4

Lot 1	501	Cactus Bloom Lane
2	505	" " "
3	509	" " "
4	513	" " "
5	601	" " "
6	605	" " "
7	609	" " "
8	701	" " "
9	705	" " "
10	709	" " "
11	801	" " "
12	805	" " "
13	809	" " "

Block 5

Lot 1	401	Torrey Pines Blvd
2	405	" " "
3	409	" " "
4	413	" " "
5	417	" " "
6	501	" " "
7	505	" " "
8	509	" " "
9	601	" " "
10	605	" " "
11	609	" " "
12	701	" " "
13	705	" " "
14	709	" " "
15	801	" " "
16	805	" " "
17	809	" " "
18	808	Cactus Bloom Lane
19	804	" " "
20	800	" " "
21	708	" " "
22	704	" " "
23	700	" " "
24	608	" " "
25	604	" " "
26	600	" " "
27	512	" " "
28	508	" " "
29	504	" " "
30	500	" " "
31	412	" " "
32	408	" " "
33	404	" " "
34	400	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot 1	6401	Hill View Avenue
2	6405	" " "
3	6409	" " "
4	6413	" " "
5	6417	" " "
6	6421	" " "
7	6425	" " "
8	6429	" " "
9	6433	" " "
10	6501	" " "
11	6505	" " "
12	6509	" " "
13	6513	" " "
14	6517	" " "
15	6521	" " "
16	6525	" " "
17	6529	" " "
18	6533	" " "
19	6537	" " "

Block 2

Lot 1	401	Plainview Street
2	405	" "
3	409	" "

Block 3

Lot 1	409	Cactus Bloom Lane
2	405	" " "
3	401	" " "
4	6420	Hill View Avenue
5	6424	" " "
6	6428	" " "
7	6432	" " "
8	6500	" " "
9	6504	" " "
10	6508	" " "
11	6512	" " "
12	6516	" " "
13	6520	" " "
14	6524	" " "
15	6528	" " "
16	6525	Villa Mesa Drive
17	6521	" " "
18	6517	" " "
19	6513	" " "
20	6509	" " "
21	6505	" " "
22	6501	" " "
23	6429	" " "
24	6425	" " "
25	6421	" " "
26	6417	" " "
27	6413	" " "

Block 4

Lot 1	501	Cactus Bloom Lane
2	505	" " "
3	509	" " "
4	513	" " "
5	601	" " "
6	605	" " "
7	609	" " "
8	701	" " "
9	705	" " "
10	709	" " "
11	801	" " "
12	805	" " "
13	809	" " "

Block 5

Lot 1	401	Torrey Pines Blvd
2	405	" " "
3	409	" " "
4	413	" " "
5	417	" " "
6	501	" " "
7	505	" " "
8	509	" " "
9	601	" " "
10	605	" " "
11	609	" " "
12	701	" " "
13	705	" " "
14	709	" " "
15	801	" " "
16	805	" " "
17	809	" " "
18	808	Cactus Bloom Lane
19	804	" " "
20	800	" " "
21	708	" " "
22	704	" " "
23	700	" " "
24	608	" " "
25	604	" " "
26	600	" " "
27	512	" " "
28	508	" " "
29	504	" " "
30	500	" " "
31	412	" " "
32	408	" " "
33	404	" " "
34	400	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot 1	6401	Hill View Avenue
2	6405	" " "
3	6409	" " "
4	6413	" " "
5	6417	" " "
6	6421	" " "
7	6425	" " "
8	6429	" " "
9	6433	" " "
10	6501	" " "
11	6505	" " "
12	6509	" " "
13	6513	" " "
14	6517	" " "
15	6521	" " "
16	6525	" " "
17	6529	" " "
18	6533	" " "
19	6537	" " "

Block 4

Lot 1	501	Cactus Bloom Lane
2	505	" " "
3	509	" " "
4	513	" " "
5	601	" " "
6	605	" " "
7	609	" " "
8	701	" " "
9	705	" " "
10	709	" " "
11	801	" " "
12	805	" " "
13	809	" " "

Block 5

Lot 1	401	Torrey Pines Blvd
2	405	" " "
3	409	" " "
4	413	" " "
5	417	" " "
6	501	" " "
7	505	" " "
8	509	" " "
9	601	" " "
10	605	" " "
11	609	" " "
12	701	" " "
13	705	" " "
14	709	" " "
15	801	" " "
16	805	" " "
17	809	" " "
18	808	Cactus Bloom Lane
19	804	" " "
20	800	" " "
21	708	" " "
22	704	" " "
23	700	" " "
24	608	" " "
25	604	" " "
26	600	" " "
27	512	" " "
28	508	" " "
29	504	" " "
30	500	" " "
31	412	" " "
32	408	" " "
33	404	" " "
34	400	" " "

Block 2

Lot 1	401	Plainview Street
2	405	" " "
3	409	" " "

Block 3

Lot 1	409	Cactus Bloom Lane
2	405	" " "
3	401	" " "
4	6420	Hill View Avenue
5	6424	" " "
6	6428	" " "
7	6432	" " "
8	6500	" " "
9	6504	" " "
10	6508	" " "
11	6512	" " "
12	6516	" " "
13	6520	" " "
14	6524	" " "
15	6528	" " "
16	6525	Villa Mesa Drive
17	6521	" " "
18	6517	" " "
19	6513	" " "
20	6509	" " "
21	6505	" " "
22	6501	" " "
23	6429	" " "
24	6425	" " "
25	6421	" " "
26	6417	" " "
27	6413	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot	1	6401	Hill View Avenue
	2	6405	" " "
	3	6409	" " "
	4	6413	" " "
	5	6417	" " "
	6	6421	" " "
	7	6425	" " "
	8	6429	" " "
	9	6433	" " "
	10	6501	" " "
	11	6505	" " "
	12	6509	" " "
	13	6513	" " "
	14	6517	" " "
	15	6521	" " "
	16	6525	" " "
	17	6529	" " "
	18	6533	" " "
	19	6537	" " "

Block 2

Lot	1	401	Plainview Street
	2	405	" " "
	3	409	" " "

Block 3

Lot	1	409	Cactus Bloom Lane
	2	405	" " "
	3	401	" " "
	4	6420	Hill View Avenue
	5	6424	" " "
	6	6428	" " "
	7	6432	" " "
	8	6500	" " "
	9	6504	" " "
	10	6508	" " "
	11	6512	" " "
	12	6516	" " "
	13	6520	" " "
	14	6524	" " "
	15	6528	" " "
	16	6525	Villa Mesa Drive
	17	6521	" " "
	18	6517	" " "
	19	6513	" " "
	20	6509	" " "
	21	6505	" " "
	22	6501	" " "
	23	6429	" " "
	24	6425	" " "
	25	6421	" " "
	26	6417	" " "
	27	6413	" " "

Block 4

Lot	1	501	Cactus Bloom Lane
	2	505	" " "
	3	509	" " "
	4	513	" " "
	5	601	" " "
	6	605	" " "
	7	609	" " "
	8	701	" " "
	9	705	" " "
	10	709	" " "
	11	801	" " "
	12	805	" " "
	13	809	" " "

Block 5

Lot	1	401	Torrey Pines Blvd
	2	405	" " "
	3	409	" " "
	4	413	" " "
	5	417	" " "
	6	501	" " "
	7	505	" " "
	8	509	" " "
	9	601	" " "
	10	605	" " "
	11	609	" " "
	12	701	" " "
	13	705	" " "
	14	709	" " "
	15	801	" " "
	16	805	" " "
	17	809	" " "
	18	808	Cactus Bloom Lane
	19	804	" " "
	20	800	" " "
	21	708	" " "
	22	704	" " "
	23	700	" " "
	24	608	" " "
	25	604	" " "
	26	600	" " "
	27	512	" " "
	28	508	" " "
	29	504	" " "
	30	500	" " "
	31	412	" " "
	32	408	" " "
	33	404	" " "
	34	400	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot	1	6401	Hill View Avenue
	2	6405	" " "
	3	6409	" " "
	4	6413	" " "
	5	6417	" " "
	6	6421	" " "
	7	6425	" " "
	8	6429	" " "
	9	6433	" " "
	10	6501	" " "
	11	6505	" " "
	12	6509	" " "
	13	6513	" " "
	14	6517	" " "
	15	6521	" " "
	16	6525	" " "
	17	6529	" " "
	18	6533	" " "
	19	6537	" " "

Block 2

Lot	1	401	Plainview Street
	2	405	" "
	3	409	" "

Block 3

Lot	1	409	Cactus Bloom Lane
	2	405	" " "
	3	401	" " "
	4	6420	Hill View Avenue
	5	6424	" " "
	6	6428	" " "
	7	6432	" " "
	8	6500	" " "
	9	6504	" " "
	10	6508	" " "
	11	6512	" " "
	12	6516	" " "
	13	6520	" " "
	14	6524	" " "
	15	6528	" " "
	16	6525	Villa Mesa Drive
	17	6521	" " "
	18	6517	" " "
	19	6513	" " "
	20	6509	" " "
	21	6505	" " "
	22	6501	" " "
	23	6429	" " "
	24	6425	" " "
	25	6421	" " "
	26	6417	" " "
	27	6413	" " "

Block 4

Lot	1	501	Cactus Bloom Lane
	2	505	" " "
	3	509	" " "
	4	513	" " "
	5	601	" " "
	6	605	" " "
	7	609	" " "
	8	701	" " "
	9	705	" " "
	10	709	" " "
	11	801	" " "
	12	805	" " "
	13	809	" " "

Block 5

Lot	1	401	Torrey Pines Blvd
	2	405	" " "
	3	409	" " "
	4	413	" " "
	5	417	" " "
	6	501	" " "
	7	505	" " "
	8	509	" " "
	9	601	" " "
	10	605	" " "
	11	609	" " "
	12	701	" " "
	13	705	" " "
	14	709	" " "
	15	801	" " "
	16	805	" " "
	17	809	" " "
	18	808	Cactus Bloom Lane
	19	804	" " "
	20	800	" " "
	21	708	" " "
	22	704	" " "
	23	700	" " "
	24	608	" " "
	25	604	" " "
	26	600	" " "
	27	512	" " "
	28	508	" " "
	29	504	" " "
	30	500	" " "
	31	412	" " "
	32	408	" " "
	33	404	" " "
	34	400	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot 1	6401	Hill View Avenue
2	6405	" " "
3	6409	" " "
4	6413	" " "
5	6417	" " "
6	6421	" " "
7	6425	" " "
8	6429	" " "
9	6433	" " "
10	6501	" " "
11	6505	" " "
12	6509	" " "
13	6513	" " "
14	6517	" " "
15	6521	" " "
16	6525	" " "
17	6529	" " "
18	6533	" " "
19	6537	" " "

Block 2

Lot 1	401	Plainview Street
2	405	" " "
3	409	" " "

Block 3

Lot 1	409	Cactus Bloom Lane
2	405	" " "
3	401	" " "
4	6420	Hill View Avenue
5	6424	" " "
6	6428	" " "
7	6432	" " "
8	6500	" " "
9	6504	" " "
10	6508	" " "
11	6512	" " "
12	6516	" " "
13	6520	" " "
14	6524	" " "
15	6528	" " "
16	6525	Villa Mesa Drive
17	6521	" " "
18	6517	" " "
19	6513	" " "
20	6509	" " "
21	6505	" " "
22	6501	" " "
23	6429	" " "
24	6425	" " "
25	6421	" " "
26	6417	" " "
27	6413	" " "

Block 4

Lot 1	501	Cactus Bloom Lane
2	505	" " "
3	509	" " "
4	513	" " "
5	601	" " "
6	605	" " "
7	609	" " "
8	701	" " "
9	705	" " "
10	709	" " "
11	801	" " "
12	805	" " "
13	809	" " "

Block 5

Lot 1	401	Torrey Pines Blvd
2	405	" " "
3	409	" " "
4	413	" " "
5	417	" " "
6	501	" " "
7	505	" " "
8	509	" " "
9	601	" " "
10	605	" " "
11	609	" " "
12	701	" " "
13	705	" " "
14	709	" " "
15	801	" " "
16	805	" " "
17	809	" " "
18	808	Cactus Bloom Lane
19	804	" " "
20	800	" " "
21	708	" " "
22	704	" " "
23	700	" " "
24	608	" " "
25	604	" " "
26	600	" " "
27	512	" " "
28	508	" " "
29	504	" " "
30	500	" " "
31	412	" " "
32	408	" " "
33	404	" " "
34	400	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
	6401	6405	6409	6413	6417	6421	6425	6429	6433	6501	6505	6509	6513	6517	6521	6525	6529	6533	6537
	Hill View Avenue	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"

Block 4

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13
	501	505	509	513	601	605	609	701	705	709	801	805	809
	Cactus Bloom Lane	"	"	"	"	"	"	"	"	"	"	"	"

Block 2

Lot	1	2	3
	401	405	409
	Plainview Street	"	"

Block 3

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27
	409	405	401	6420	6424	6428	6432	6500	6504	6508	6512	6516	6520	6524	6528	6525	6521	6517	6513	6509	6505	6501	6429	6425	6421	6417	6413
	Cactus Bloom Lane	"	"	Hill View Avenue	"	"	"	"	"	"	"	"	"	"	"	Villa Mesa Drive	"	"	"	"	"	"	"	"	"	"	"

Block 5

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34
	401	405	409	413	417	501	505	509	601	605	609	701	705	709	801	805	809	808	804	800	708	704	700	608	604	600	512	508	504	500	412	408	404	400
	Torrey Pines Blvd	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	Cactus Bloom Lane	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot	1	6401	Hill View Avenue
	2	6405	" " "
	3	6409	" " "
	4	6413	" " "
	5	6417	" " "
	6	6421	" " "
	7	6425	" " "
	8	6429	" " "
	9	6433	" " "
	10	6501	" " "
	11	6505	" " "
	12	6509	" " "
	13	6513	" " "
	14	6517	" " "
	15	6521	" " "
	16	6525	" " "
	17	6529	" " "
	18	6533	" " "
	19	6537	" " "

Block 2

Lot	1	401	Plainview Street
	2	405	" " "
	3	409	" " "

Block 3

Lot	1	409	Cactus Bloom Lane
	2	405	" " "
	3	401	" " "
	4	6420	Hill View Avenue
	5	6424	" " "
	6	6428	" " "
	7	6432	" " "
	8	6500	" " "
	9	6504	" " "
	10	6508	" " "
	11	6512	" " "
	12	6516	" " "
	13	6520	" " "
	14	6524	" " "
	15	6528	" " "
	16	6525	Villa Mesa Drive
	17	6521	" " "
	18	6517	" " "
	19	6513	" " "
	20	6509	" " "
	21	6505	" " "
	22	6501	" " "
	23	6429	" " "
	24	6425	" " "
	25	6421	" " "
	26	6417	" " "
	27	6413	" " "

Block 4

Lot	1	501	Cactus Bloom Lane
	2	505	" " "
	3	509	" " "
	4	513	" " "
	5	601	" " "
	6	605	" " "
	7	609	" " "
	8	701	" " "
	9	705	" " "
	10	709	" " "
	11	801	" " "
	12	805	" " "
	13	809	" " "

Block 5

Lot	1	401	Torrey Pines Blvd
	2	405	" " "
	3	409	" " "
	4	413	" " "
	5	417	" " "
	6	501	" " "
	7	505	" " "
	8	509	" " "
	9	601	" " "
	10	605	" " "
	11	609	" " "
	12	701	" " "
	13	705	" " "
	14	709	" " "
	15	801	" " "
	16	805	" " "
	17	809	" " "
	18	808	Cactus Bloom Lane
	19	804	" " "
	20	800	" " "
	21	708	" " "
	22	704	" " "
	23	700	" " "
	24	608	" " "
	25	604	" " "
	26	600	" " "
	27	512	" " "
	28	508	" " "
	29	504	" " "
	30	500	" " "
	31	412	" " "
	32	408	" " "
	33	404	" " "
	34	400	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
	6401	6405	6409	6413	6417	6421	6425	6429	6433	6501	6505	6509	6513	6517	6521	6525	6529	6533	6537
	Hill View Avenue	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"

Block 4

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13
	501	505	509	513	601	605	609	701	705	709	801	805	809
	Cactus Bloom Lane	"	"	"	"	"	"	"	"	"	"	"	"

Block 2

Lot	1	2	3
	401	405	409
	Plainview Street	"	"

Block 3

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27
	409	405	401	6420	6424	6428	6432	6500	6504	6508	6512	6516	6520	6524	6528	6525	6521	6517	6513	6509	6505	6501	6429	6425	6421	6417	6413
	Cactus Bloom Lane	"	"	Hill View Avenue	"	"	"	"	"	"	"	"	"	"	"	Villa Mesa Drive	"	"	"	"	"	"	"	"	"	"	"

Block 5

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34
	401	405	409	413	417	501	505	509	601	605	609	701	705	709	801	805	809	808	804	800	708	704	700	608	604	600	512	508	504	500	412	408	404	400
	Torrey Pines Blvd	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	Cactus Bloom Lane	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot 1	6401	Hill View Avenue
2	6405	" " "
3	6409	" " "
4	6413	" " "
5	6417	" " "
6	6421	" " "
7	6425	" " "
8	6429	" " "
9	6433	" " "
10	6501	" " "
11	6505	" " "
12	6509	" " "
13	6513	" " "
14	6517	" " "
15	6521	" " "
16	6525	" " "
17	6529	" " "
18	6533	" " "
19	6537	" " "

Block 4

Lot 1	501	Cactus Bloom Lane
2	505	" " "
3	509	" " "
4	513	" " "
5	601	" " "
6	605	" " "
7	609	" " "
8	701	" " "
9	705	" " "
10	709	" " "
11	801	" " "
12	805	" " "
13	809	" " "

Block 5

Lot 1	401	Torrey Pines Blvd
2	405	" " "
3	409	" " "
4	413	" " "
5	417	" " "
6	501	" " "
7	505	" " "
8	509	" " "
9	601	" " "
10	605	" " "
11	609	" " "
12	701	" " "
13	705	" " "
14	709	" " "
15	801	" " "
16	805	" " "
17	809	" " "
18	808	Cactus Bloom Lane
19	804	" " "
20	800	" " "
21	708	" " "
22	704	" " "
23	700	" " "
24	608	" " "
25	604	" " "
26	600	" " "
27	512	" " "
28	508	" " "
29	504	" " "
30	500	" " "
31	412	" " "
32	408	" " "
33	404	" " "
34	400	" " "

Block 2

Lot 1	401	Plainview Street
2	405	" " "
3	409	" " "

Block 3

Lot 1	409	Cactus Bloom Lane
2	405	" " "
3	401	" " "
4	6420	Hill View Avenue
5	6424	" " "
6	6428	" " "
7	6432	" " "
8	6500	" " "
9	6504	" " "
10	6508	" " "
11	6512	" " "
12	6516	" " "
13	6520	" " "
14	6524	" " "
15	6528	" " "
16	6525	Villa Mesa Drive
17	6521	" " "
18	6517	" " "
19	6513	" " "
20	6509	" " "
21	6505	" " "
22	6501	" " "
23	6429	" " "
24	6425	" " "
25	6421	" " "
26	6417	" " "
27	6413	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot	1	6401	Hill View Avenue
	2	6405	" " "
	3	6409	" " "
	4	6413	" " "
	5	6417	" " "
	6	6421	" " "
	7	6425	" " "
	8	6429	" " "
	9	6433	" " "
	10	6501	" " "
	11	6505	" " "
	12	6509	" " "
	13	6513	" " "
	14	6517	" " "
	15	6521	" " "
	16	6525	" " "
	17	6529	" " "
	18	6533	" " "
	19	6537	" " "

Block 2

Lot	1	401	Plainview Street
	2	405	" "
	3	409	" "

Block 3

Lot	1	409	Cactus Bloom Lane
	2	405	" " "
	3	401	" " "
	4	6420	Hill View Avenue
	5	6424	" " "
	6	6428	" " "
	7	6432	" " "
	8	6500	" " "
	9	6504	" " "
	10	6508	" " "
	11	6512	" " "
	12	6516	" " "
	13	6520	" " "
	14	6524	" " "
	15	6528	" " "
	16	6525	Villa Mesa Drive
	17	6521	" " "
	18	6517	" " "
	19	6513	" " "
	20	6509	" " "
	21	6505	" " "
	22	6501	" " "
	23	6429	" " "
	24	6425	" " "
	25	6421	" " "
	26	6417	" " "
	27	6413	" " "

Block 4

Lot	1	501	Cactus Bloom Lane
	2	505	" " "
	3	509	" " "
	4	513	" " "
	5	601	" " "
	6	605	" " "
	7	609	" " "
	8	701	" " "
	9	705	" " "
	10	709	" " "
	11	801	" " "
	12	805	" " "
	13	809	" " "

Block 5

Lot	1	401	Torrey Pines Blvd
	2	405	" " "
	3	409	" " "
	4	413	" " "
	5	417	" " "
	6	501	" " "
	7	505	" " "
	8	509	" " "
	9	601	" " "
	10	605	" " "
	11	609	" " "
	12	701	" " "
	13	705	" " "
	14	709	" " "
	15	801	" " "
	16	805	" " "
	17	809	" " "
	18	808	Cactus Bloom Lane
	19	804	" " "
	20	800	" " "
	21	708	" " "
	22	704	" " "
	23	700	" " "
	24	608	" " "
	25	604	" " "
	26	600	" " "
	27	512	" " "
	28	508	" " "
	29	504	" " "
	30	500	" " "
	31	412	" " "
	32	408	" " "
	33	404	" " "
	34	400	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
	6401	6405	6409	6413	6417	6421	6425	6429	6433	6501	6505	6509	6513	6517	6521	6525	6529	6533	6537
	Hill View Avenue	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"

Block 4

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13
	501	505	509	513	601	605	609	701	705	709	801	805	809
	Cactus Bloom Lane	"	"	"	"	"	"	"	"	"	"	"	"

Block 2

Lot	1	2	3
	401	405	409
	Plainview Street	"	"

Block 3

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27
	409	405	401	6420	6424	6428	6432	6500	6504	6508	6512	6516	6520	6524	6528	6525	6521	6517	6513	6509	6505	6501	6429	6425	6421	6417	6413
	Cactus Bloom Lane	"	"	Hill View Avenue	"	"	"	"	"	"	"	"	"	"	"	Villa Mesa Drive	"	"	"	"	"	"	"	"	"	"	"

Block 5

Lot	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34
	401	405	409	413	417	501	505	509	601	605	609	701	705	709	801	805	809	808	804	800	708	704	700	608	604	600	512	508	504	500	412	408	404	400
	Torrey Pines Blvd	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	Cactus Bloom Lane	"	"	"	"	"	"	"	"	"	"	"	"	"	"	"	

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot 1	6401	Hill View Avenue
2	6405	" " "
3	6409	" " "
4	6413	" " "
5	6417	" " "
6	6421	" " "
7	6425	" " "
8	6429	" " "
9	6433	" " "
10	6501	" " "
11	6505	" " "
12	6509	" " "
13	6513	" " "
14	6517	" " "
15	6521	" " "
16	6525	" " "
17	6529	" " "
18	6533	" " "
19	6537	" " "

Block 2

Lot 1	401	Plainview Street
2	405	" " "
3	409	" " "

Block 3

Lot 1	409	Cactus Bloom Lane
2	405	" " "
3	401	" " "
4	6420	Hill View Avenue
5	6424	" " "
6	6428	" " "
7	6432	" " "
8	6500	" " "
9	6504	" " "
10	6508	" " "
11	6512	" " "
12	6516	" " "
13	6520	" " "
14	6524	" " "
15	6528	" " "
16	6525	Villa Mesa Drive
17	6521	" " "
18	6517	" " "
19	6513	" " "
20	6509	" " "
21	6505	" " "
22	6501	" " "
23	6429	" " "
24	6425	" " "
25	6421	" " "
26	6417	" " "
27	6413	" " "

Block 4

Lot 1	501	Cactus Bloom Lane
2	505	" " "
3	509	" " "
4	513	" " "
5	601	" " "
6	605	" " "
7	609	" " "
8	701	" " "
9	705	" " "
10	709	" " "
11	801	" " "
12	805	" " "
13	809	" " "

Block 5

Lot 1	401	Torrey Pines Blvd
2	405	" " "
3	409	" " "
4	413	" " "
5	417	" " "
6	501	" " "
7	505	" " "
8	509	" " "
9	601	" " "
10	605	" " "
11	609	" " "
12	701	" " "
13	705	" " "
14	709	" " "
15	801	" " "
16	805	" " "
17	809	" " "
18	808	Cactus Bloom Lane
19	804	" " "
20	800	" " "
21	708	" " "
22	704	" " "
23	700	" " "
24	608	" " "
25	604	" " "
26	600	" " "
27	512	" " "
28	508	" " "
29	504	" " "
30	500	" " "
31	412	" " "
32	408	" " "
33	404	" " "
34	400	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot	1	6401	Hill View Avenue
	2	6405	" " "
	3	6409	" " "
	4	6413	" " "
	5	6417	" " "
	6	6421	" " "
	7	6425	" " "
	8	6429	" " "
	9	6433	" " "
	10	6501	" " "
	11	6505	" " "
	12	6509	" " "
	13	6513	" " "
	14	6517	" " "
	15	6521	" " "
	16	6525	" " "
	17	6529	" " "
	18	6533	" " "
	19	6537	" " "

Block 2

Lot	1	401	Plainview Street
	2	405	" " "
	3	409	" " "

Block 3

Lot	1	409	Cactus Bloom Lane
	2	405	" " "
	3	401	" " "
	4	6420	Hill View Avenue
	5	6424	" " "
	6	6428	" " "
	7	6432	" " "
	8	6500	" " "
	9	6504	" " "
	10	6508	" " "
	11	6512	" " "
	12	6516	" " "
	13	6520	" " "
	14	6524	" " "
	15	6528	" " "
	16	6525	Villa Mesa Drive
	17	6521	" " "
	18	6517	" " "
	19	6513	" " "
	20	6509	" " "
	21	6505	" " "
	22	6501	" " "
	23	6429	" " "
	24	6425	" " "
	25	6421	" " "
	26	6417	" " "
	27	6413	" " "

Block 4

Lot	1	501	Cactus Bloom Lane
	2	505	" " "
	3	509	" " "
	4	513	" " "
	5	601	" " "
	6	605	" " "
	7	609	" " "
	8	701	" " "
	9	705	" " "
	10	709	" " "
	11	801	" " "
	12	805	" " "
	13	809	" " "

Block 5

Lot	1	401	Torrey Pines Blvd
	2	405	" " "
	3	409	" " "
	4	413	" " "
	5	417	" " "
	6	501	" " "
	7	505	" " "
	8	509	" " "
	9	601	" " "
	10	605	" " "
	11	609	" " "
	12	701	" " "
	13	705	" " "
	14	709	" " "
	15	801	" " "
	16	805	" " "
	17	809	" " "
	18	808	Cactus Bloom Lane
	19	804	" " "
	20	800	" " "
	21	708	" " "
	22	704	" " "
	23	700	" " "
	24	608	" " "
	25	604	" " "
	26	600	" " "
	27	512	" " "
	28	508	" " "
	29	504	" " "
	30	500	" " "
	31	412	" " "
	32	408	" " "
	33	404	" " "
	34	400	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot 1	6401	Hill View Avenue
2	6405	" " "
3	6409	" " "
4	6413	" " "
5	6417	" " "
6	6421	" " "
7	6425	" " "
8	6429	" " "
9	6433	" " "
10	6501	" " "
11	6505	" " "
12	6509	" " "
13	6513	" " "
14	6517	" " "
15	6521	" " "
16	6525	" " "
17	6529	" " "
18	6533	" " "
19	6537	" " "

Block 4

Lot 1	501	Cactus Bloom Lane
2	505	" " "
3	509	" " "
4	513	" " "
5	601	" " "
6	605	" " "
7	609	" " "
8	701	" " "
9	705	" " "
10	709	" " "
11	801	" " "
12	805	" " "
13	809	" " "

Block 5

Lot 1	401	Torrey Pines Blvd
2	405	" " "
3	409	" " "
4	413	" " "
5	417	" " "
6	501	" " "
7	505	" " "
8	509	" " "
9	601	" " "
10	605	" " "
11	609	" " "
12	701	" " "
13	705	" " "
14	709	" " "
15	801	" " "
16	805	" " "
17	809	" " "
18	808	Cactus Bloom Lane
19	804	" " "
20	800	" " "
21	708	" " "
22	704	" " "
23	700	" " "
24	608	" " "
25	604	" " "
26	600	" " "
27	512	" " "
28	508	" " "
29	504	" " "
30	500	" " "
31	412	" " "
32	408	" " "
33	404	" " "
34	400	" " "

Block 2

Lot 1	401	Plainview Street
2	405	" " "
3	409	" " "

Block 3

Lot 1	409	Cactus Bloom Lane
2	405	" " "
3	401	" " "
4	6420	Hill View Avenue
5	6424	" " "
6	6428	" " "
7	6432	" " "
8	6500	" " "
9	6504	" " "
10	6508	" " "
11	6512	" " "
12	6516	" " "
13	6520	" " "
14	6524	" " "
15	6528	" " "
16	6525	Villa Mesa Drive
17	6521	" " "
18	6517	" " "
19	6513	" " "
20	6509	" " "
21	6505	" " "
22	6501	" " "
23	6429	" " "
24	6425	" " "
25	6421	" " "
26	6417	" " "
27	6413	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot 1	6401	Hill View Avenue
2	6405	" " "
3	6409	" " "
4	6413	" " "
5	6417	" " "
6	6421	" " "
7	6425	" " "
8	6429	" " "
9	6433	" " "
10	6501	" " "
11	6505	" " "
12	6509	" " "
13	6513	" " "
14	6517	" " "
15	6521	" " "
16	6525	" " "
17	6529	" " "
18	6533	" " "
19	6537	" " "

Block 4

Lot 1	501	Cactus Bloom Lane
2	505	" " "
3	509	" " "
4	513	" " "
5	601	" " "
6	605	" " "
7	609	" " "
8	701	" " "
9	705	" " "
10	709	" " "
11	801	" " "
12	805	" " "
13	809	" " "

Block 5

Lot 1	401	Torrey Pines Blvd
2	405	" " "
3	409	" " "
4	413	" " "
5	417	" " "
6	501	" " "
7	505	" " "
8	509	" " "
9	601	" " "
10	605	" " "
11	609	" " "
12	701	" " "
13	705	" " "
14	709	" " "
15	801	" " "
16	805	" " "
17	809	" " "
18	808	Cactus Bloom Lane
19	804	" " "
20	800	" " "
21	708	" " "
22	704	" " "
23	700	" " "
24	608	" " "
25	604	" " "
26	600	" " "
27	512	" " "
28	508	" " "
29	504	" " "
30	500	" " "
31	412	" " "
32	408	" " "
33	404	" " "
34	400	" " "

Block 2

Lot 1	401	Plainview Street
2	405	" " "
3	409	" " "

Block 3

Lot 1	409	Cactus Bloom Lane
2	405	" " "
3	401	" " "
4	6420	Hill View Avenue
5	6424	" " "
6	6428	" " "
7	6432	" " "
8	6500	" " "
9	6504	" " "
10	6508	" " "
11	6512	" " "
12	6516	" " "
13	6520	" " "
14	6524	" " "
15	6528	" " "
16	6525	Villa Mesa Drive
17	6521	" " "
18	6517	" " "
19	6513	" " "
20	6509	" " "
21	6505	" " "
22	6501	" " "
23	6429	" " "
24	6425	" " "
25	6421	" " "
26	6417	" " "
27	6413	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot	1	6401	Hill View Avenue
	2	6405	" " "
	3	6409	" " "
	4	6413	" " "
	5	6417	" " "
	6	6421	" " "
	7	6425	" " "
	8	6429	" " "
	9	6433	" " "
	10	6501	" " "
	11	6505	" " "
	12	6509	" " "
	13	6513	" " "
	14	6517	" " "
	15	6521	" " "
	16	6525	" " "
	17	6529	" " "
	18	6533	" " "
	19	6537	" " "

Block 2

Lot	1	401	Plainview Street
	2	405	" " "
	3	409	" " "

Block 3

Lot	1	409	Cactus Bloom Lane
	2	405	" " "
	3	401	" " "
	4	6420	Hill View Avenue
	5	6424	" " "
	6	6428	" " "
	7	6432	" " "
	8	6500	" " "
	9	6504	" " "
	10	6508	" " "
	11	6512	" " "
	12	6516	" " "
	13	6520	" " "
	14	6524	" " "
	15	6528	" " "
	16	6525	Villa Mesa Drive
	17	6521	" " "
	18	6517	" " "
	19	6513	" " "
	20	6509	" " "
	21	6505	" " "
	22	6501	" " "
	23	6429	" " "
	24	6425	" " "
	25	6421	" " "
	26	6417	" " "
	27	6413	" " "

Block 4

Lot	1	501	Cactus Bloom Lane
	2	505	" " "
	3	509	" " "
	4	513	" " "
	5	601	" " "
	6	605	" " "
	7	609	" " "
	8	701	" " "
	9	705	" " "
	10	709	" " "
	11	801	" " "
	12	805	" " "
	13	809	" " "

Block 5

Lot	1	401	Torrey Pines Blvd
	2	405	" " "
	3	409	" " "
	4	413	" " "
	5	417	" " "
	6	501	" " "
	7	505	" " "
	8	509	" " "
	9	601	" " "
	10	605	" " "
	11	609	" " "
	12	701	" " "
	13	705	" " "
	14	709	" " "
	15	801	" " "
	16	805	" " "
	17	809	" " "
	18	808	Cactus Bloom Lane
	19	804	" " "
	20	800	" " "
	21	708	" " "
	22	704	" " "
	23	700	" " "
	24	608	" " "
	25	604	" " "
	26	600	" " "
	27	512	" " "
	28	508	" " "
	29	504	" " "
	30	500	" " "
	31	412	" " "
	32	408	" " "
	33	404	" " "
	34	400	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972

TORREY PINES VILLAS

Block 1

Lot	1	6401	Hill View Avenue
	2	6405	" " "
	3	6409	" " "
	4	6413	" " "
	5	6417	" " "
	6	6421	" " "
	7	6425	" " "
	8	6429	" " "
	9	6433	" " "
	10	6501	" " "
	11	6505	" " "
	12	6509	" " "
	13	6513	" " "
	14	6517	" " "
	15	6521	" " "
	16	6525	" " "
	17	6529	" " "
	18	6533	" " "
	19	6537	" " "

Block 4

Lot	1	501	Cactus Bloom Lane
	2	505	" " "
	3	509	" " "
	4	513	" " "
	5	601	" " "
	6	605	" " "
	7	609	" " "
	8	701	" " "
	9	705	" " "
	10	709	" " "
	11	801	" " "
	12	805	" " "
	13	809	" " "

Block 5

Lot	1	401	Torrey Pines Blvd
	2	405	" " "
	3	409	" " "
	4	413	" " "
	5	417	" " "
	6	501	" " "
	7	505	" " "
	8	509	" " "
	9	601	" " "
	10	605	" " "
	11	609	" " "
	12	701	" " "
	13	705	" " "
	14	709	" " "
	15	801	" " "
	16	805	" " "
	17	809	" " "
	18	808	Cactus Bloom Lane
	19	804	" " "
	20	800	" " "
	21	708	" " "
	22	704	" " "
	23	700	" " "
	24	608	" " "
	25	604	" " "
	26	600	" " "
	27	512	" " "
	28	508	" " "
	29	504	" " "
	30	500	" " "
	31	412	" " "
	32	408	" " "
	33	404	" " "
	34	400	" " "

Block 2

Lot	1	401	Plainview Street
	2	405	" " "
	3	409	" " "

Block 3

Lot	1	409	Cactus Bloom Lane
	2	405	" " "
	3	401	" " "
	4	6420	Hill View Avenue
	5	6424	" " "
	6	6428	" " "
	7	6432	" " "
	8	6500	" " "
	9	6504	" " "
	10	6508	" " "
	11	6512	" " "
	12	6516	" " "
	13	6520	" " "
	14	6524	" " "
	15	6528	" " "
	16	6525	Villa Mesa Drive
	17	6521	" " "
	18	6517	" " "
	19	6513	" " "
	20	6509	" " "
	21	6505	" " "
	22	6501	" " "
	23	6429	" " "
	24	6425	" " "
	25	6421	" " "
	26	6417	" " "
	27	6413	" " "

Richard L. Williams
 Planning Assistant
 January 7, 1972