

☐ PERMIT
NUMBER

91108516

INSPECTION
NUMBER

JOB ADDRESS

9516 Sierra Summit Ave

LOT NO

BLOCK NO

384-4747

SUBDIVISION NAME

FIRE DEPT MAP NO

Canyon Elec

JOB PHONE

CALL IN DATE

6-3-91

CALL IN TIME

2 303 P

SCHEDULE DATE

INSPECTOR NO

INSPECTOR NAME

84

INSPECTION
REQUESTED

filed

- ① Attach grounding to ground bus at panel
- ② Disconnect doesn't have 36" clearance
- ③ Recept not allowed within 10'
- ④ Bond ^{spa} pool light with #4
- ⑤ Bolt equip to pad
- ⑥ Breaker for spa service must be 2 pole
single throw

☐ PARTIAL
INSPECTION

☐ PARTIAL
APPROVAL (P)

PARTIAL DESCRIPTION

☐ APPROVED
(A)

☐ STOP
WORK (S)

☐ COMMENTS
(C)

☐ TEMPORARY
APPROVAL (T) - UNTIL

☐ HOLD
(H)

☒ REJECTED (R)

REINSPECTION REQUIRED CALL *799 2071

☐ REFEE (F)
REINSPECTION FEE REQUIRED PAY AT CITY HALL
3RD FLOOR 400 E STEWART STREET
☐ PERMIT
REQUIRED
INSPECTOR
SIGNATURE

K Ward

INSPECTION DATE

6-5-91

☐ PROJECT
COMPLETE
BRING HARD CARD WITH FIRE QUALITY CONTROL & PLANNING APPROVALS
SIGNED OFF TO BLDG & SAFETY FOR C of O ISSUANCE (Commercial Only)IF YOU HAVE ANY QUESTIONS ON THIS INSPECTION YOU MAY
CALL THE INSPECTOR FROM 7 00 A M 7 15 A M OR 2 45 P M 3 00 P M AT