

2613 Durango

Bridget Babbington-Butler 1-19-90

DEPARTMENT OF BUILDING & SAFETY - CITY OF LAS VEGAS

JOB ADDRESS 2613 Durango		PERMIT NO.	
LOT NO.	MAP NO.	INSPECTOR 65	DATE
SUBMISSION NAME Admiral Point		PHONE	
INSPECTOR SIGNATURE LB 65	INSPECTION DATE 9-19-89		
("JAY + POLLEY") 363-4444? OFF FRONT GATE - WEST AMERICAN GROUP? - INVESTIGATION - - KNOCKED ON ALL SIX DOORS NO ONE ANSWERS, IF "JAY + POLLEY" CALL BACK, GET THEIR LAST NAMES AND PHONE NUMBER, AND UNIT NUMBER!			
<input type="checkbox"/> PARTIAL INSPECTION - DESCRIPTION:			
<input type="checkbox"/> APPROVED		<input type="checkbox"/> PERMIT REQUIRED	
<input type="checkbox"/> STOP WORK			
<input type="checkbox"/> REJECTED - CORRECTION NOTICE - REINSPECTION REQUIRED CALL 799-2071			
INSPECT	DESCRIPTION	INSPECT	DESCRIPTION
<input type="checkbox"/> B-1	FOOTING, LAYOUT, REBAR, ZONING	<input type="checkbox"/> P-1	ON SITE SEWER
<input type="checkbox"/> B-2	STEM WALL - FORMS & REBAR	<input type="checkbox"/> P-2	ON SITE WATER
<input type="checkbox"/> B-3	PRE-SLAB	<input type="checkbox"/> P-3	BUILDING SEWER (ARD LINES)
<input type="checkbox"/> B-4	ROOF SHEATHING	<input type="checkbox"/> P-4	UNDERSLAB DRAINING
<input type="checkbox"/> B-5	FRAMING	<input type="checkbox"/> P-5	TOP OUTLET GAS, WASTE
<input type="checkbox"/> B-6	INSULATION	<input type="checkbox"/> P-6	FINAL GAS TEST
<input type="checkbox"/> B-7	DRYWALL NAILING	<input type="checkbox"/> P-7	FINAL PLUMBING
<input type="checkbox"/> B-8	EXTERIOR LATH/STUCCO		
<input type="checkbox"/> B-9	WALL CHOUT & STEEL	<input type="checkbox"/> M-1	ROUGH VENT
<input type="checkbox"/> B-10	POOL PRE-GUNITE	<input type="checkbox"/> M-2	HOOD
<input type="checkbox"/> B-11	POOL PRE-PLASTER / FINAL	<input type="checkbox"/> M-3	FINAL MECHANICAL
<input type="checkbox"/> B-12	BUILDING FINAL		
<input type="checkbox"/> B-13	CERT. OF OCC.	<input type="checkbox"/> X-1	KICKER / FLUSH
<input type="checkbox"/> X-2		<input type="checkbox"/> X-2	UNDERGROUND HYDRO
<input type="checkbox"/> X-3		<input type="checkbox"/> X-3	UNDERGROUND FINAL/FLOW
<input type="checkbox"/> X-4		<input type="checkbox"/> X-4	SPRINKLER SYSTEM HYDRO
<input type="checkbox"/> X-5		<input type="checkbox"/> X-5	FIRE ALARM
<input type="checkbox"/> X-6		<input type="checkbox"/> X-6	OTHER:
<input type="checkbox"/> X-7		<input type="checkbox"/> X-7	FINAL FIRE
<input type="checkbox"/> E-1		<input type="checkbox"/> E-1	UNDERGROUND ELECTRICAL
<input type="checkbox"/> E-2		<input type="checkbox"/> E-2	ROUGH ELECTRICAL
<input type="checkbox"/> E-3		<input type="checkbox"/> E-3	LOW VOLTAGE ELECTRICAL
<input type="checkbox"/> E-4		<input type="checkbox"/> E-4	SIGN INSPECTION
<input type="checkbox"/> E-5		<input type="checkbox"/> E-5	FINAL ELECTRICAL
<input type="checkbox"/> E-6		<input type="checkbox"/> E-6	TEMP POWER
<input type="checkbox"/> FINAL INSPECTION	BRING HARD CARD WITH FIRE, QUALITY CONTROL & PLANNING APPROVALS SIGNED OFF TO BLDG & SAFETY FOR C. of O. ISSUANCE (Commercial Only)		

FOR ASSISTANCE - CALL: 386-6251

DEPARTMENT OF BUILDING & SAFETY CITY OF LAS VEGAS

JOB ADDRESS 2613 S. DURAN		PERMIT NO.	
LOT NO.	MAP NO.	INSPECTOR 65	DATE
SUBDIVISION NAME Alameda Point		PHONE	
INSPECTOR SIGNATURE LB65		INSPECTION DATE 9-22-89	
(AMERICAN GROUP #)			
REPAIR LOOSE TILES AT			
VARIOUS LOCATIONS AS NOTED!			
REPAIR VENT PIPE ON S.W. CORNER			
ADJUST POOL GATE TO SELF CLOSE			
REMOVE ALL TEMPORARY			
POWER. POWER STILL IN PROTECT!			
REFER TO SENIOR INSP. #43			
CORRECT 10-10-89 AND			
CALL FOR INSPECTIONS			
<input type="checkbox"/> PARTIAL INSPECTION - DESCRIPTION:			
<input checked="" type="checkbox"/> APPROVED		<input type="checkbox"/> PERMIT REQUIRED	
<input checked="" type="checkbox"/> REJECTED (CORRECTION NOTICE)		<input type="checkbox"/> STOP WORK	
REINSPECTION REQUIRED CALL 799-2071			
INSPCT	DESCRIPTION	INSPCT	DESCRIPTION
<input type="checkbox"/> B-1	FOOTING, LAYOUT, REBAR, ZONING	<input type="checkbox"/> P-1	ON SITE SEWER
<input type="checkbox"/> B-2	STEM WALL + FORMS & REBAR	<input type="checkbox"/> P-2	ON SIDE WATER
<input type="checkbox"/> B-3	PRE-SLAB	<input type="checkbox"/> P-3	BUILDING SEWER (YARD LINES)
<input type="checkbox"/> B-4	ROOF SHEATHING	<input type="checkbox"/> P-4	UNDERSLAB PLUMBING
<input type="checkbox"/> B-5	FRAMING	<input type="checkbox"/> P-5	TOP OUT-WATER, GAS, WASTE
<input type="checkbox"/> B-6	INSULATION	<input type="checkbox"/> P-6	FINAL GAS TEST
<input type="checkbox"/> B-7	DRYWALL NAILING	<input type="checkbox"/> P-7	FINAL PLUMBING
<input type="checkbox"/> B-8	EXTERIOR LATH/STUCCO		
<input type="checkbox"/> B-9	WALL GROUT & STEEL	<input type="checkbox"/> M-1	ROUGH MECHANICAL
<input type="checkbox"/> B-10	POOL PRE-GUNITE	<input type="checkbox"/> M-2	FINAL MECHANICAL
<input type="checkbox"/> B-11	POOL PRE-PLASTER / FINAL		
<input type="checkbox"/> B-12	BUILDING FINAL		
<input type="checkbox"/> B-13	CERT. OF OCC.	<input type="checkbox"/> X-1	KICKER / FLUSH
		<input type="checkbox"/> X-2	UNDERGROUND ELECTRICAL
		<input type="checkbox"/> X-3	UNDERGROUND FINAL/FLOW
		<input type="checkbox"/> X-4	SPRAY SYSTEM/HYDRO
		<input type="checkbox"/> X-5	ALARM
		<input type="checkbox"/> X-7	FINAL FIRE
		<input type="checkbox"/> E-1	UNDERGROUND ELECTRICAL
		<input type="checkbox"/> E-2	ROUGH ELECTRICAL
		<input type="checkbox"/> E-3	LOW VOLTAGE ELECTRICAL
		<input type="checkbox"/> E-4	SIGN INSPECTION
		<input type="checkbox"/> E-5	FINAL ELECTRICAL
		<input type="checkbox"/> E-6	TEMP POWER
<input type="checkbox"/> FINAL INSPECTION		BRING HARD CARD WITH FIRE, QUALITY CONTROL & PLANNING APPROVALS SIGNED OFF TO BLDG & SAFETY FOR C. OF ISSUANCE (Commercial Only)	

FOR ASSISTANCE - CALL: 386-8251

CITY OF LAS VEGAS, DIVISION of BUILDING and SAFETY
INFORMATION INSPECTION RECORD

GIVE TO #43
ATTN SENIOR #43
C. MOORE

JOB ~~ADMIRAL~~ ADMIRAL POINT
ADDRESS 2613 S. DURANGO
DATE 9-22-89
INSPECTOR Lou BRUNSON #65
TYPE OF INSPECTION COMPLAINT

WALKED AROUND BUILDING W/ RICK
MC CARTHY AND RILES YOUNG

NOTED FOLLOWING PROBLEMS

ACTION REQUIRED

CONTACT IS
RICK MC CARTHY
737-6525

- 1- LOOSE TILE ON N.E. CORNER
- 2- VENT PIPE IN ROOF FLASHING MISSING, OR PUSHED DOWN N.E. CORNER
- 3- LOOSE ROW OF TILES OVER GARAGE OPENING OF UNIT # 101 S.W. CORNER

REMARKS/INFORMATION

OWNER IS
AMERICAN
GROUP #

- 4- LOOSE ROW OF TILES OVER GARAGE METERS, S.W. CORNER
- 5- ADJUST SELF-CLOSING GATE OF SWIMMING POOL
- 6- REMOVE TEMPORARY POWER POLES THRU-OUT PROJECT

SIGNATURE

OWNER
OWNER
COMPLAINT

Lou # 65

CITY OF LAS VEGAS, DIVISION of BUILDING and SAFETY

INFORMATION INSPECTION RECORD

GIVE TO #43
ATTN SENIOR #43
C. MOORE

JOB ~~ADMIRAL~~ ADMIRAL POINT
ADDRESS 7613 S. DURANGO
DATE 1-9-22-89
INSPECTOR Lou BRANSON #65
TYPE OF INSPECTION COMPLAINT

WALKED AROUND BUILDING W/ RICK MC CARTHY AND MILES YOUNG

NOTED FOLLOWING PROBLEMS

ACTION REQUIRED

CONTACT IS
REK MC CARTHY
737-6525

- 1- LOOSE TILE ON N.E. CORNER
- 2- VENT PIPE IN ROOF FLASHING MISSING, OR PUSHED DOWN N.E. CORNER
- 3- LOOSE ROW OF TILES OVER GARAGE OPENING OF UNIT # 101 S.W. CORNER
- 4- LOOSE ROW OF TILES OVER GARAGE METERS, S.W. CORNER
- 5- ADJUST SELF-CLOSING GATE OF SWIMMING POOL
- 6- REMOVE TEMPORARY POWER POLES THRU-OUT PROJECT

REMARKS/INFORMATION

OWNER IS
AMERICAN
GROUP II

SIGNATURE

OWNER COMPLAINT

Lou # 65