

·1111 FREMONT ·

Lila Collins 2-1-82

DEPT. of BLDG. & SAFETY - CITY of LAS VEGAS, NEVADA  
OWNER: FRANKLIN BROS. ADDRESS: 1111 Fremont St. DATE: 2-27-57  
GEN. CONT. OZZIE KRAFT TYPE OF STRUCTURE: SWIMMING POOL  
PERMIT NO. 28282 LEGAL DESCRIPTION: Lot 3, Bl. 1, Ladd's Addn

LOCATION & FLOOR ELEVATION  
FOOTING  
FOUNDATIONS  
WALL STEEL  
BOND BEAM STEEL  
FRAMING & ROOF SHEATHING  
STEEL FABRICATION  
CONNECTIONS & PAINTING  
LATHING  
PLASTER  
SCRATCH  
BROWN  
FINAL BLDG.  
GRADING & DRAINAGE  
ON-SITE PARKING  
ENG. APPROVAL OF OFF-SITE IMPROVEMENTS

PLUMBING CONT.  
PERMIT NO.  
HEAT & VENT. CONT.  
PERMIT NO.  
SEWER CONT.  
PERMIT NO.  
ROUGH SOIL  
ROUGH WATER  
SEWER OR SEPTIC TANK  
TOR-OUT  
ROUGH GAS  
ROUGH DUCT  
FINAL PLUMBING  
FINAL HEATING  
FINAL GAS

TEMP. POLE CONT.  
PERMIT NO.  
INSPECTION  
ELECTRICAL CONT.  
PERMIT NO.  
OUTLETS  
MOTORS  
SLAB  
ROUGH  
FINAL ROUGH  
FIXTURE CONT.  
PERMIT NO.  
FIXTURES  
FINAL FIXTURE  
APPROVED FOR METER

APPROVED for OCCUPANCY: \_\_\_\_\_ INSPECTOR \_\_\_\_\_ DATE \_\_\_\_\_  
\* PLEASE NOTE REMARKS ON REVERSE SIDE 1111 Fremont St. - SWIMMING POOL (LUCKY MOTEL) 2/27/57 28.04

DEPARTMENT OF BUILDING & SAFETY  
CITY OF LAS VEGAS, NEVADA

KARDEX CARD  
SIGN

OWNER: Lucky Motel ADDRESS: 1111 E. Fremont DATE: 9-28-71  
CONTRACTOR: Yesco PERMIT NO.: 1019  
LOT \_\_\_\_\_ BLOCK \_\_\_\_\_ SUBDIVISION \_\_\_\_\_

LOCATION \_\_\_\_\_  
SHOP (WIRING, CONST.) \_\_\_\_\_  
SITE (BLDG., ETC.) \_\_\_\_\_  
INST. (SERV: STRUCT.) \_\_\_\_\_  
BILLBOARD \_\_\_\_\_  
ELECTRIFIED \_\_\_\_\_  
FINAL A.B. 2-14-72

ELECT. ROUGH \_\_\_\_\_  
ELECT. FINAL \_\_\_\_\_

23.07 D ADDRESS 1111 E. Fremont LOG NO. \_\_\_\_\_ AREA M-298

Hebbie Sughran 11-5-85

BUILDING DEPARTMENT  
CITY OF LAS VEGAS

CORRECTION NOTICE

Lucky Motel *(Corrected 10-22-85 S.A.S.)*

Job Located at 1111 E. Fremont

I have this day inspected this structure and these premises and have found the following violations of City and/or State laws governing same:

- ① All holes and openings in the walls of the hot water heater room must be patched and sealed. The crawl space must be sealed with 3/8" double x sheef rock to prevent any gas from entering this space.
  - ② The pressure relief lines must be extended to an approved location for each water heater.
- You have 48 hours to comply by 10-9-85.

You are hereby notified to correct above violation and call for re-inspection.

Date 10-7-85 Thomas A. Nugino  
Inspector

23.03 Do not remove this tag!

BUILDING DEPARTMENT  
CITY OF LAS VEGAS

CORRECTION NOTICE

Lucky Motel *(Corrected 10-22-85 S.A.S.)*

Job Located at 1111 E. Fremont

I have this day inspected this structure and these premises and have found the following violations of City and/or State laws governing same:

- ③ The venting on the 3 water heaters is wrong. The vents shall not enter a common vent on the same elevation. The end cap on the common vent pipe is not properly sealed.
  - ④ The upper combustion air opening must have 1/4 mesh screen covering it.
- You have 10 days to comply by 10-18-85.

You are hereby notified to correct above violation and call for re-inspection.

Date 10-7-85 Thomas A. Nugino  
Inspector

23.03 Do not remove this tag!