

6201 FAWN CIR.

**DEPT. of BLDG. & SAFETY - CITY of LAS VEGAS, NEVADA**

OWNER: Sproul Homes, Inc. ADDRESS: 6201 Fawn Circle DATE: Sent. 5, 1961

GEN. CONT. Sproul Homes, Inc. TYPE OF STRUCTURE: S. F. DWG.

PERMIT NO. 5917 LEGAL DESCRIPTION: L. 66, Bk. 1, Chas. Hts. 28-A

|                                      |                                              |                                              |
|--------------------------------------|----------------------------------------------|----------------------------------------------|
| LOCATION: <u>Fireplace Ftg.</u>      | PLUMBING CONT. <u>Waited</u>                 | TEMP. POLE CONT. <u>Waited</u>               |
| FOOTINGS: <u>Waited</u>              | PERMIT NO. <u>13418</u> DATE <u>9-11-61</u>  | PERMIT NO. <u>Waited</u> DATE <u>Waited</u>  |
| FOUNDATIONS: <u>Waited</u>           | HEAT. & VENT. CONT. <u>Waited</u>            | INSPECTION: <u>Waited</u> DATE <u>Waited</u> |
| FLOOR: <u>Waited</u>                 | PERMIT NO. <u>13418</u> DATE <u>11-26-61</u> | ELECTRICAL CONT. <u>Waited</u>               |
| ANCHOR BOLTS: <u>Waited</u>          | SEWER CONT. <u>Waited</u>                    | PERMIT NO. <u>Waited</u> DATE <u>Waited</u>  |
| WALL: STEEL <u>Waited</u>            | PERMIT NO. <u>3617</u> DATE <u>9-11-61</u>   | OUTLETS: <u>43</u>                           |
| COLUMN: STEEL <u>Waited</u>          | ROUGH SOIL: <u>Waited</u>                    | MOTORS: <u>Waited</u> H.P. <u>Waited</u>     |
| BEAM: STEEL <u>Waited</u>            | ROUGH WATER: <u>Waited</u>                   | SLAB: <u>Waited</u>                          |
| FRAMING: <u>Waited</u>               | TOP-OUT: <u>Waited</u>                       | ROUGH: <u>Waited</u>                         |
| ROOF SHEATHING: <u>Waited</u>        | ROUGH GAS: <u>Waited</u>                     | FINAL ROUGH: <u>Waited</u>                   |
| STEEL FABRICATION: <u>Waited</u>     | AC ROUGH DUCT: <u>Waited</u>                 | FIXTURES CONT. <u>Waited</u>                 |
| STEEL CONNECTION: <u>Waited</u>      | REF. ROUGH PIPING: <u>Waited</u>             | PERMIT NO. <u>Waited</u> DATE <u>Waited</u>  |
| LATHING: <u>Waited</u>               | SEWER: <u>Waited</u>                         | FIXTURES: <u>Waited</u>                      |
| BACKING: <u>Waited</u>               | SEPIC TANK: <u>Waited</u>                    | FINAL FIXTURE: <u>Waited</u>                 |
| PLASTER: <u>Waited</u>               | FINAL PLUMBING: <u>Waited</u>                | URBAN REDEVELOPMENT APPROVAL: <u>Waited</u>  |
| FINAL BLDG. <u>Waited</u>            | FINAL GAS: <u>Waited</u>                     |                                              |
| GRADING & DRAINAGE: <u>Waited</u>    | FINAL HEATING: <u>Waited</u>                 |                                              |
| ON-SITE PARKING: <u>Waited</u>       | FINAL AIR COND.: <u>Waited</u>               |                                              |
| ENG. APPROVAL OF: <u>Waited</u>      | FINAL REFRIG.: <u>Waited</u>                 |                                              |
| OFF-SITE IMPROVEMENTS: <u>Waited</u> |                                              |                                              |

INSPECTOR: Waited DATE: Waited

APPROVED FOR OCCUPANCY: Waited

APPROVED FOR METER: Waited

PLEASE NOTE: REMARKS ON REVERSE SIDE

6201 Fawn Circle 9/5/61 Log# T-17 AREA: 23.04