

A. 9008 Mountain Gate
B. 9012 Mountain Gate
C. 9016 Mountain Gate



**WESTERN
TECHNOLOGIES
INC.**

3611 West Tompkins Avenue
Las Vegas, Nevada 89103
(702) 798-8050

FIELD REPORT

**REVIEW OF FOUNDATION CONDITIONS
(POST ON JOBSITE)**

Client DEL WEBB Job No. 4149J090
Project SUN CITY Lab./Invoice No. _____
Location SUMMERLIN Report No. _____ Date 6-21-87
Prime Contractor CURTIS JONES Superintendent Renny Scrima
Time of Report 8:30

In accordance with the request of DEL WEBB
a review of the excavations for foundations on the above referenced project was made.

The purpose of the review was to:

☒ Verify conformity of depths of foundation excavations to requirements of project plans and/or specifications.

☐ Verify that the undisturbed bearing soils exposed by the excavations were of the nature and condition anticipated by WT Soil Engineering Report No. _____

☒ Check for debris and/or loose or disturbed soils in bottom of foundations excavations.

☒ Check conformity of foundation dimensions with project plan requirements.

☒ Check conformity of foundation reinforcement in the excavations with project requirements.

☐ Other _____

With the exceptions stated below, the review revealed that:

☒ Depth of foundation excavations (did) (did not) meet project requirements.

☐ Soil bearing recommendations presented in WT Soil Engineering Report No. _____ for foundations bearing on _____ (do) (do not) remain applicable.

☒ Foundation excavations (did) (did not) contain debris and/or loose or disturbed soil. Subsequent debris, loose or disturbed soil should be removed from bottoms of excavations before placing concrete.

☒ Excavation dimensions (did) (did not) meet minimum project plan requirements for foundation dimensions.

☒ Sizes and locations of foundation reinforcing steel in the excavation (did) (did not) meet project plan requirements.

☐ Other _____

The following foundation excavations were reviewed:

UNIT B
LOT 137, 138
SR# 410, 411

UNIT 10
LOT 11, 12
SR# 414, 415

Exceptions and/or remarks:

Review By _____