.3000 S. Rancho (3).
INSPECTOR'S REPORT BK

Don Hood 1-5-88

CONCRETE PLACEMENT LOG

TRUCK NO.	~~TICKET~~ NO.	APPROVED MIX DESIGN	LOAD SIZE (CUBIC YARDS)	CUMULATIVE LOAD SIZE	TIME TRUCK LEFT PLANT	TIME TRUCK ARRIVED ON SITE	TIME TRUCK EMPTY	SLUMP TEST (INCHES)	WATER ADDED AT JOB SITE (CONTRACTOR'S RESPONSIBILITY)	AIR TEMP - F	CONC TEMP - F	PLACEMENT LOCATION	REMARKS
89	157943	CH N-156-1	8	8	8:30	9:10.	9:45	3"				Pad footings 3 building D	
110	162926		10	18	10:10	10:40	11:10						Test taken

DATE OF PLACEMENT: 6-3-87 **PROJECT NAME:** Palms 3000 S Rancho

Dona Hoesly 1-5-88

CONCRETE PLACEMENT LOG

TRUCK NO.	TICKET NO.	APPROVED MIX DESIGN	LOAD SIZE (CUBIC YARDS)	CUMULATIVE LOAD SIZE	TIME TRUCK LEFT PLANT	TIME TRUCK ARRIVED ON SITE	TIME TRUCK EMPTY	SLUMP TEST (INCHES)	WATER ADDED AT JOB SITE (CONTRACTOR'S RESPONSIBILITY)	AIR TEMP - F	CONC TEMP - F	PLACEMENT LOCATION	REMARKS
94	152028	CM N-150-1	10	10	12:39	1:30	1:50	6¼				footings Building D	Test Taken
107	152029		10	20	12:44	1:35	2:10						
103	15 2855		10	30	2:11	2:45	3:00						
113	152808		2	32	3:41	4:10	4:20						

DATE OF PLACEMENT: 6-8-87 PROJECT NAME: Palms 3000 S. Rancho