

BEFORE AND AFTER PHOTOS
820 S. Valley View Blvd., Las Vegas, NV 89107

VIP Before Photo



Main view of the building complex facing south from the driveway on neighbors side.



**Photos of Landscaping before purchased.
Trash and debris and dead trees, shrubs and tree stumps**



West side of building along back street facing Hyde Middle School. Dead weeds, trash and two large tree stumps.

#

Initial changes to landscaped areas with native barrel cacti varieties. Areas look much better. Waiting for amendment approval before installing metal Saguaros and more barrel cacti and rock gravel.



Planted native Cacti



View of front landscaped area after planting looking southward.



Examples of metal Cacti one block north of building showing how the metal barrels and Saguaros may look.